40OK-5111H

ASSEMBLY INSTRUCTION

1. INDOOR USE ONLY
2. ~~REPLACE THE BULB AFTER THE BULB GETS COOL.~~

Assembly steps:



Step 1. Hang bead strings(L) on (A4) and (A3). And repeat with the rest bead strings(L) total 8pcs.

Step 2. Hang bead strings(B) on (A2).

Step 3. Mount the shade (C) to the nipple(A4) and secure with loop(D).

Step 4. Mount ceiling fitting

Step 4-1. Tighten loop(F)on the tube(G).

Step 4-2.Loosen screw(J)and pass canopy (H) over the tube(G).

Step 4-3.Tighten loop(I) on the tube(G).

Step 4-4. Pass the main wire through the links of chain,loop(F),canopy(H), tube(G)and loop(I).

Step4-5.Attach first link and last link(E) of chain to the loops(D) and(F).

Step 4-6. Connect wire to the power supply cord.

Step 4-7. Raise the canopy(H)to ceiling and secure it by tightening the screw(J).

Step 4-8. Hang the Loop(I)on the hook on ceiling.

Step 5. Turn in the bulb to the socket.

After completed the above instruction, please check once more to ensure its safety. Then you may turn the power on. If the external cable or cord is damaged it shall be replaced by qualified person to avoid hazard.